




## TOPAS MKI is obsolete

Kongsberg Maritime aims to provide support to current and previous generations of products. However, the availability of key components is a limiting factor for support over time.

### TOPAS PS18 MKI and TOPAS PS40 MKI

The TOPAS MKI transceiver unit can be recognized by the twisted ribbon cable on the front of the control shelf of the cabinet.



The TOPAS PS18 MKI control shelf

The TOPAS MKI transceiver unit uses electronic components, backplane and wiring that are no longer available and can neither be repaired, replaced or upgraded. Any malfunctioning MKI transceiver unit must therefore be replaced in its entirety by the MKII transceiver cabinet.

This applies to the MKI revisions of TOPAS PS18 and TOPAS PS40 and relates to systems using a plug in NI Data Acquisition card which is labelled as "National Instruments".

Sales and production of the TOPAS MKI systems was stopped before 2017.

### Support information

Should you need support for your TOPAS system you may contact your Kongsberg Maritime office. You can also contact our 24/7 customer support.

Global support 24/7: +47 3303 2407  
 E-mail support: [km.support@kongsberg.com](mailto:km.support@kongsberg.com)  
 E-mail sales: [km.sales@km.kongsberg.com](mailto:km.sales@km.kongsberg.com)  
[www.kongsberg.com](http://www.kongsberg.com)

KONGSBERG MARITIME  
 Strandpromenaden 50  
 P.O. Box 111  
 N-3191 Horten, Norway  
 Switchboard: +47 815 73 700

TOPAS MKI  
 PS18 AND PS40

